



ILA-USMX JOINT SAFETY COMMITTEE

OSH ALERT 2019-07 [14 April 2019]

Inspection Notice IMMEDIATE ACTION REQUIRED

3M® DBI-SALA® ExoFit NEX™ Harnesses



The manufacturer of the 3M-ExoFit-NEX fall protection harness has distributed a product notification, alerting users of a potential “D” Ring defect.

Should your fall protection system incorporate the use of the 3M-ExoFit-NEX, we urge review and implementation of the guidance provided via this link:

<https://www.mcaa.org/wp-content/uploads/2019/04/3M-ExoFit-NEX-Inspection-Notice-April-16th-2019.pdf>

Got a question about this particular subject? Write to the JSC at: blueoceana@optonline.net

Working Together For The Benefit Of All

ILA-USMX OSH Alerts are devised to reflect the best possible information and guidance, and are products of diligent research and the most up to date subject matter knowledge. Consequently, while the information contained herein is believed to be accurate, owing to a host of factors ILA-USMX can convey no direct or implied warranty relative to the reliance of parties upon content.